

PoYo™ Putty 40

Mix & Apply-By-Hand Mold Putty



www.smooth-on.com

PRODUCT OVERVIEW

PoYo™ Putty 40 is a two-component mold making silicone (tin catalyst) that can be mixed and applied “on site”—directly to almost any model. PoYo™ Putty will hold any vertical surface and capture even the finest detail—perfect for making strong rubber molds that can be used within minutes. **Use Less—Do More:** Because PoYo™ is applied as a thin layer, less material is used, saving you money. Molds are also lightweight, making them easier to handle.

Pot life and cure time can be adjusted (faster or slower) by varying the amount of Part B catalyst. **User Friendly—PoYo™ Putty** can be measured and mixed by volume (no scale necessary). It will stick to itself and other silicone rubbers, giving the user many application options or for using as a silicone rubber repair material.

PoYo™ Putty has been used to make molds of valuable antiques and archeological models and can be used to make fast molds of sculpture, prototypes, candles, picture frames, coins, etc. You can cast wax, gypsum and a variety of resins into PoYo™ Putty molds.

PROCESSING RECOMMENDATIONS

PREPARATION...

Safety - Use in a properly ventilated area (“room size” ventilation). Wear safety glasses, long sleeves and rubber gloves to minimize contamination risk. Wear vinyl gloves only. Latex gloves will inhibit the cure of the rubber.

Store and use material at room temperature (73°F/23°C). Warmer temperatures will drastically reduce working time and cure time. Storing material at warmer temperatures will also reduce the usable shelf life of unused material. These products have a limited shelf life and should be used as soon as possible.

TECHNICAL OVERVIEW

Mix Ratio: 100A:6B by weight or 20A:1B by volume

Mixed Viscosity: Putty

Specific Gravity, g/cc: 1.30 (ASTM D-1475)

Specific Volume, cu. in./lb.: 21.31 (ASTM D-1475)

Pot Life: 3-5 minutes (73°F/23°C) (ASTM D-2471)

Cure time: 30 minutes (73°F/23°C)

Color: Light Pink

Shore A Hardness: 40 (ASTM D-2240)

Tensile Strength, psi: 450 (ASTM D-412)

Elongation @ Break: 250% (ASTM D-412)

Die B Tear Strength, pli: 85 (ASTM D-624)

Shrinkage, in./in.: 0.003 (ASTM D-2566)

Useful Temp. Range: -65°F to 400°F (-53°C to 205°C)

* All values measured after 7 days at 73°F/23°C

Applying A Sealer - PoYo™ Putty silicone rubber may be inhibited by sulfur-based clays resulting in tackiness at the pattern interface. If compatibility between the rubber and the surface is a concern, a small-scale test is recommended. Apply a small amount of rubber onto a non-critical area of the pattern. Inhibition has occurred if the rubber is gummy or uncured after the recommended cure time has passed. To prevent inhibition, a “barrier coat” of clear acrylic lacquer sprayed directly onto the pattern is usually effective. **Wear Gloves** - This product is mixed by hand and wearing gloves is required. Wear vinyl gloves. Latex gloves will inhibit the cure of the rubber.

Measuring - Materials should be stored and used at room temperature (73° F / 23°C). This product has a limited shelf life and should be used as soon as possible. Wear safety glasses, long sleeves and rubber gloves to minimize contamination risk.

Hint: Pre-kneading Part A (working in your hands for one minute prior to mixing with Part B) will make the two components easier to mix.

Measuring By Weight: Using an accurate gram scale, weight out 100 parts A—level by hand into bottom of container. Dispense 6 parts B into center of flattened Part A. Follow mixing directions below. **Measuring By Volume:** The by volume mix ratio is about 20A:1B.

Visual Approach: Measure an amount of Part A approximately equal to the size of a golf ball onto the palm of your hand and create an indentation. Dispense an amount of Part B approximately equal to the size of a small marble into the center of the Part A indentation. (Hint: It is better to start out with less Part B and add more if needed, rather than too much Part B).

MIXING & APPLYING...

Mixing - Fold the Part A around the Part B and knead aggressively with thumb and forefinger. Continue folding until a uniform light-pink color is attained. Make sure that all color streaks have been eliminated.

Safety First!

The Material Safety Data Sheet (MSDS) for this or any Smooth-On product should be read prior to use and is available upon request from Smooth-On. All Smooth-On products are safe to use if directions are read and followed carefully.

Keep Out of Reach of Children

BE CAREFUL - Avoid contact with eyes. Silicone polymers are generally non-irritating to the eyes however a slight transient irritation is possible. Flush eyes with water for 15 minutes and seek medical attention. Remove from skin with waterless hand cleaner followed by soap and water. Children should not use this product without adult supervision.

IMPORTANT - The information contained in this bulletin is considered accurate. However, no warranty is expressed or implied regarding the accuracy of the data, the results to be obtained from the use thereof, or that any such use will not infringe upon a patent. User shall determine the suitability of the product for the intended application and assume all risk and liability whatsoever in connection therewith.

Applying the Rubber - PoYo™ can be applied directly onto almost any model surface (see preparation above) except skin. After mixing Parts A & B as directed above, flatten mixture and gently press into model detail. Spread evenly over model surface, maintaining about a 3/8" (1 cm) thickness. Mix and apply more as needed, connecting and smoothing seams of different batches together.

Be Careful - If your original is made of modeling clay or other soft material, pressing putty onto model surface may affect model detail. You may want to first apply a thin "print coat" using Mold Max™ silicone and back up using PoYo™ Putty.

CURING & PERFORMANCE...

Allow the mold to cure 30 minutes at room temperature (73°F/23°C) before removing from model surface. Adding more Part B can reduce cure time. Adding less Part B will give you a longer working time and lengthen demold time. If applying a support shell, apply the shell before removing the rubber mold from the model.

Applying A Support Shell - Usually, PoYo™ Putty molds will be too thin to support themselves during casting. A support shell made of Plasti-Paste™ or Matrix NEO™ and chopped fiber can be applied over the mold surface.

Using The Mold - When first made, silicone rubber molds exhibit natural release characteristics. Depending on what is being cast into the mold, mold lubricity may be depleted over time and parts will begin to stick.

Applying A Release Agent - Although not usually necessary, a release agent will make demolding easier when casting into most surfaces. Ease Release™ 200 is a proven release agent for releasing silicone from silicone or other surfaces. Mann Ease Release™ products are available from Smooth-On or your Smooth-On distributor.

IMPORTANT: To ensure thorough coverage, lightly brush the release agent with a soft brush over all surfaces of the mold or model. Follow with a light mist coating and let the release agent dry for 30 minutes.

Because no two applications are quite the same, a small test application to determine suitability for your project is recommended if performance of this material is in question.



Call Us Anytime With Questions About Your Application.

Toll-free: (800) 381-1733 Fax: (610) 252-6200

www.smooth-on.com is loaded with information about mold making, casting and more.