# **E-POX-EE<sup>TM</sup> KLEENER** Hand Kleener for Removing Resins & More!



www.smooth-on.com

## **PRODUCT OVERVIEW**

**E-POX-EE KLEENER™** is a unique industrial hand cleaner made especially for removing unreacted liquid epoxy, polyester, urethanes and other resins from the skin. It will also remove liquid paint, lacquer and grease.

# **DIRECTIONS FOR BEST RESULTS**

#### DO NOT WET HANDS BEFORE USING

- 1. Shake well before using.
- 2. Dispense a liberal amount of E-POX-EE KLEENER<sup>™</sup> onto the hands.
- 3. Work well into resin contaminated areas.
- 4. Wash hands with soap and water.
- 5. Repeat as necessary.

### SAFETY FIRST!

- For Industrial Use Only Keep Away From Children
- If ingested, contact Poison Control in USA:1-800-222-1222 You Can Also Call; Chem-Tel in USA: 1-888-255-3924
- Do not use in proximity to flame or ignition sources. Contains Mineral Spirits.
- Store and use at room temperature.
- Do not use in proximity to the eyes. If eye contamination occurs, flush eyes with water for 15 minutes and seek medical attention.
- · Refer to Material Safety Data Sheet available at www.smooth-on.com

#### Safety First!

The Material Safety Data Sheet (MSDS) for this or any Smooth-On product should be read prior to use and is available upon request from Smooth-On. All Smooth-On products are safe to use if directions are read and followed carefully.

#### Keep Out of Reach of Children

*IMPORTANT* - The information contained in this bulletin is considered accurate. However, no warranty is expressed or implied regarding the accuracy of the data, the results to be obtained from the use thereof, or that any such use will not infringe upon a patent. User shall determine the suitability of the product for the intended application and assume all risk and liability whatsoever in connection therewith.



# Call Us Anytime With Questions About Your Application. Toll-free: (800) 381-1733 Fax: (610) 252-6200

www.smooth-on.com is loaded with information about mold making, casting and more.